



## Specialty Products **FAQ**

Part Numbers 93080/93090

### Mustang II Dropped Spindles

**Q1: The caliper bracket will not fit properly on the new spindle. What can be done?**

**A1:** Some caliper brackets may not fit properly because of a casting protrusion on the back of the spindle housing. This can easily be remedied by grinding of enough of the castings so the brake caliper bracket will fit properly. Fit your caliper bracket and grind off just enough to make mounting bolt holes line up properly. Do not remove any more material than necessary.

